QUALITY CONTROL

Name of the Work:	Deselting and Resetting of footpath slabs at St.Mary's school road in 1st M/R Ward No.13
Job No:	013-13-000143
Work order No:	144/14-15 D:28.07.2014
BR No:	625/28.10.2014

On verification of quality control test reports available in the file and also from inspection report of Technical Team Deployed for this purpose generally the work executed is satisfactory. Compliance of Quality Control Test Reports as per MORT&H at this stage is not feasible since this work was executed one years back.

Assistant Executive Engineer
Shettyhalli Sub Division
Bruhat Bengaluru Mahanagara Palike

Executive Engineer
Dasarahalli Division, Dasarahalli Zone
Bruhat Bengaluru Mahanagara Palike